

Xerox copies of the following letters and articles are available from The National for a SASE (self-addressed-stamped-businesssize envelope). Some of the articles consist of more than 1 page (piece of paper). The number in parentheses at the end of the title indicates the number of pages. Four pages plus envelope equal 1 first class stamp. If requesting a number of Library Items, send the proper amount for postage. The National will provide the envelope. For items #14, 16, 26, 27, 28, 80, 91, & 107 please send two stamps and no envelope. Specify number and title of article(s) requested, several require a minimal charge as noted.

1. Battery Charger Aids All-Electric Refrigerator - Wilson Call, Bakersfield, CA, 1973 Cortez.
2. Automatics Failure To Start When Hot - Bert Howard, San Dimas, CA; Fred Franke, Sunnyvale, CA; John Boll, Ironton, OH. (3)
3. Replacing Window Runners - Woodie Merrill, Maitland, FL.
4. Quieting the South Wind Heater - Howard Swank, Wilmington, DE.
5. Shim Torsion Bars to Restore Coach Height - Ray Stokoe, Ballston Lake, NY.
6. Suspension Arm Repair - Frank Lewis - Austin, TX, 1965 Cortez. (2)
7. Laundry Chute - Mickey Smith, Hollywood, FL, 1971 Cortez.
8. Installing Cruise Control - Glen Fotre, Pocatello, ID, 1971 Cortez.
9. Putting in 2 New Batteries, 6 or 12 Volt? Connections, Calculations, Comments - Olin Mapes, Jacksonville, FL, 1972 Cortez.
10. Chrysler /6 Choke Stove Substitution - Joel Smith, Huntington Beach, CA.
11. Preparing Cortez Exterior For Painting - Carl Perry, Portland, OR, 1964 Cortez.
12. Repairing Clark Model Front Door Lock - Jay Jensen, Canyon Lake, CA. (2)
13. Bicycle Rack For Side Door Cortez - Don McCall, Drexel, NC, 1972 Cortez.
14. Winterizing Your Cortez - Allan Powell, Lewiston, NY, 1978 Cortez & Marv Gale, Shaker Hgts, OH. (7)
15. Servex Refrigerator, Service & Troubleshooting - Rudy Nelson, Austin, MN.
16. Primer, 1973 Cortez - Rudy Nelson, Austin, MN. (9)
17. The Power Alternative - Turbocharging. (2)
18. U-Joint Failure, 1965 Cortez - Frank Lewis, Austin, TX. (2) — 450\* torque
19. Spare Tire Carrier Modification For Larger Tires - Don McCall, Drexel, NC, 1972 Cortez & Earl Mayer, Milwaukee, WI. (2)
20. Suburban Heater Information Sheet. Service, Diagnosis & Corrective Measures - Al Chamberlin, Roswell, NM.
21. Schematic 115 to 12v Converter For '69 Cortez - Jack Davis, Silver City, NM.
22. Step By Step Instructions For Removing & Reinstalling Suburban Furnace In 1973 Cortez - Bill Townsend, Ventura, CA. (2)
23. Field Testing & Jury-Rigging 120 Amp Motorola Charging System, 1966 Cortez - Carl Johnson, Chatham, NJ.
24. Supplemental Heat While Running, 1966 Cortez - Carl Johnson, Chatham, NJ.
25. An 18x22" Blueprint Schematic Interior Wiring of 1972 Cortez (probably good for other automatics) - Bill Townsend, Ventura, CA. Send \$3 check to The National to cover copy & postage costs.
26. Wiring Diagrams for 1972 Cortez (probably valid for other automatics). (1) Fuse & circuit breaker identification; (2) Interior Block diagram; (3) Battery compartment wiring; (4) Wire gauge size for 12v system; (5) Battery charging system wiring; (6) Battery compartment wiring showing option switch to charge engine battery when plugged into 110v; (7) Radio speaker wiring - Olin Mapes, Jacksonville, FL. + Battery Wiring Diagram - Don McCall, Drexel, NC. (5)
27. The Great Adventure - Don & Floss Davis, Long Grove, IL, 1979 Cortez. Chronicles their tour through the Northeast & Maritime Provinces of Canada. Send 3 stamps, no envelope.
28. Mexico ... Porque No! - Jack & Marvine Davis, Silver City, NM, 1969 Cortez. A short guide and travelog by Jack & Marvine who travel to Mexico frequently.
29. Air Shocks Up Front, Long Throw In Back - Don Majerus, Lakeport, CA, 1969 Cortez. Sketches, dimensions, and part numbers.
30. Transmission oil filter installation.
31. Engine Starting Problem, Ballast Resistor, 1966 Cortez - Carl Johnson, Chatham, NJ.
32. Ball Joint Replacement, Clark Models - Carl Johnson, Chatham, NJ.
33. Cortez Lamp Chart - Olin Mapes, Jacksonville, FL, 1972 Cortez. A list of bulb numbers showing base type, candle power, wattage, and typical usage.
34. Interior Air Conditioner Shroud Removal '72 Cortez - Olin Mapes, Jacksonville, FL.
35. Convert Rear Bath Kent for Queen-size Bed - Bill Becker, St. Louis Park, MN.
36. Replacing South Wind Heater with Therm'x Catalytic, Clark Models - Ray Minturn, Anacortes, WA.
37. Wiring Diagrams for 110 & 12 volt Systems, 1964 Cortez - John Nape, Chicago, IL.
38. Electrical Independence With a Solar Battery Charger - Bill Raborg, Frazier Park, CA, 1968 Cortez. (4)
39. Cortez Rim Conversion from 8.25x17.5 to 8.25x16.5 - R.L. Sprague, Evendale, OH. (3)
40. Rebuilding Upper Ball Joints '72 Cortez, drawings & instructions - Olin Mapes, Jacksonville, FL & Emerson Brooks, Richardson, TX. (2)
41. Original letter and drawing showing Clark Cortez Ball Joint Wear Limits - Tim Verschuyt, Palo Alto, CA, 1965 Cortez.
42. Solve Holding Tank Odor Problems Without Chemicals - Frank Freda, Montecito, CA.



43. Repairing Polyethelene Holding Tanks - Bob Dennett, Tucson, AZ & Harry Futoran, Long Beach, CA. (2)
44. The 12-volt Charging System.
45. Front Wheel Bearing Service Bulletin. (2)
46. Hoist for RV Tire Changing.
47. Adapter Plate for Chevy 327 Engine to Clark Transmission - Burk Gattie, Klamath Falls, OR, 1968 Cortez.
48. Kitchen Sink Water To Gray Water Holding Tank, Kent Side Bath Model - Joel Smith, Huntington Beach, CA.
49. Heater Core Removal & Modification, Kent Model - Joel Smith, Huntington Beach, CA.
50. Radiator Removal & Reinstallation, Kent Model, Joel Smith, Huntington Beach, CA. (2)
51. Passenger Seat Guard Rail, Bed Position - Borge Jensen, Central Point, OR.
52. Rear Cross-Member & Gas Tank Modification, '72 and Later Side Door Models ONLY - Frank Freda, Montecito, CA.
53. Information Sheet With Part Numbers For Making Up Lug Wrench Using Proto Professional Line of Tools - Ray Hoffins, Longmont, CO.
54. Vacuum Hose Layout To & From Distributor With Instructions On How To Test The Distributor Vacuum Control Switch for '71 & '72 Cortez with 455 Engine - Olin Mapes, Jacksonville, FL.
55. Tips & Service Schedule for U-Joints for '65 Cortez & Other Clark Models - Tim Verschuyf, Palo Alto, CA.
56. Spare Tire Carrier Modification To Ease The Job of Getting the Spare On & Off the Coach - Ed Fagar, Downey, CA.
57. A 1970 Article From Peterson Publishing Co. Book on Adapting the Olds 455 Engine to Existing Clark Manual Transmission - Carl Johnson, Chatham, NJ. (3)
58. Modification To Strengthen & Improve Front Bumper Arrangement on '73 Cortez with Drawings, Instructions, and Materials List - Gayle Roofe, Bryan, TX.
59. Part Numbers and Dimensions On Enlarging the Rear Wheel Bearings on '72 Cortez & All Kent Models - Olin Mapes, Jacksonville, FL.
60. Brake Drum Assembly Diagram for Kent Models Showing NAPA Equivalent Part Numbers - Olin Mapes, Jacksonville, FL.
61. Rear Bumper Reinforcement & Trailer Hitch for Kent Models, Drawings & Instructions - Gayle Roofe, Bryan, TX.
62. Engine Oil Cooler Installation for Kent Models, Materials List, Instructions & Drawings - Gayle Roofe, Bryan, TX.
63. Drawing & Instructions for Device to Check Rear Crossmember Movement - Kent side door models - Earl Mayer, Milwaukee, WI.
64. Cruise & Drive to Alaska - Emerson Brooks, Richardson, TX.
65. Clark Cortez Front Wheel Bearings - 450 Foot Pounds of Torque with Tools You Probably Already Have (set-up drawing included) - Tim Verschuyf, Palo Alto, CA.
66. Instructions and Drawing for Locating and Replacing Fuel Gauge Sending Unit on Rear Bath Kent Model Coaches - Olin Mapes, Jacksonville, FL.
67. Instruction Sheet on Overhaul of the Saginaw Rotary Valve Gear Assembly & Pitman Shaft Seal Kit, with part numbers for Clark models - A.E. Chamberlin, Roswell, NM.
68. Alaska Adventure - Narrative of June 1984 trip - Ross & Arline McClurg, Spokane, WA.
69. Plans for Multi-purpose Platform to Raise Passenger Foot-well Area, or Use as wheel chocks or as ramps to level coach - Olin Mapes, Jacksonville, FL.
70. Lug Wrench Stand - Barney Tarshes, Rogue River, OR.
71. Instructions & Drawings To Modify Hinge on Side Door Model To Open Flat Against Side of Coach - Bob Valpey, San Luis Obispo, CA. (2)
72. Drawing on Replacement of Fuel Sending Unit on Clark Models Without Dropping the Gas Tank - Jack Costa, Sepulveda, CA.
73. A 1965 Standard Oil newsletter sent to its service station operators with some Cortez facts, specifications, and part numbers for the Clark model - Vic Victorson, Long Beach, CA. (2)
74. Know Your Tires, a four page article by Dr. Karl Kopetzky published in the RV Digest - Paul Myrehn, Indianapolis, IN. (3)
75. Cortez Service Bulletin, Wheel Alignment & Steering Adjustment for Kent Model Coaches and those with 12x16.5 tires (revised 7/21/77) - Joel C. Smith, Huntington Beach, CA. (3)
76. Bleeding Disc Brakes - Warren Wipson, Santa Cruz, CA.
77. Cortez Service Bulletin, Paint Color Numbers for 1973 - Ted Miguel, Key West, FL.
78. Instructions, parts list, and wiring diagram for making Ground Fault Circuit Interrupter Unit for use between shore power and coach - Al Kubichck, Short Hills, NJ.
79. An 18"x24" Blueprint Wiring & Schematic Onan Eng/Gen Control. Send \$3 check to The National to cover copy & postage costs.
80. Phasing Out of Leaded Gasoline. A series of articles and letters from Oldsmobile, Onan Generator, the National Newsletter, and FMCA Magazine. (4)
81. Pictorial diagram showing the engine air conditioner wiring for the '69 (8 cylinder) Cortez. Olin Mapes, Jacksonville, FL.
82. Pictorial diagram 22"x34" showing the engine air conditioner wiring for Kent model coaches. Olin Mapes, Jacksonville, FL. (2)
83. Pictorial diagram showing the cruise control mechanical and electrical connections for Kent model coaches. Olin Mapes, Jacksonville, FL.



84. Pictorial diagram showing engine vacuum line layout for Kent model coaches. Olin Mapes, Jacksonville, FL.
85. Pictorial diagram of front wheel brake hose assembly with notation of fittings and part numbers for Kent model. Olin Mapes, Jacksonville, FL.
86. A series of 5 pictorial diagrams as follows: (1) Fuse block with each labelled for its circuit assignment and which terminals are hot in relation to ignition switch on or off; (2) Shore line AC plug connections; (3) Ignition and starting system 12 volt block diagram; (4) Engine compartment wiring diagram; (5) A 12/110 volt interconnection block wiring diagram. All are referenced from a '72 side door and applicable to Kent models. Olin Mapes, Jacksonville, FL. (3)
87. Wiring diagram and instructions on replacing the bathroom vent with a more modern unit which features an electric motor to raise and lower the vent, a fan, and interior light. Wiring instructions for optional remote control from the driver's seat are also included. Bobb Partridge, Terrell, TX.
88. Drawing and instructions for replacement of the original wellnuts used to secure the luggage pod to the roof and upgrading to a more permanent fix. Bobb Partridge, Terrell, TX.
89. Mechanic's Shop Guide. This 11x17 inch chart has a torque conversion table, one on inches, decimal, and metric, drill and tap sizes, a segment on analyzing vacuum gauge readings, and tips on how to interpret what is viewed thru the air conditioner sight gauge. Bill Townsend, Ventura, CA.
90. This item combined with item 40. *Clark Model Engine Wiring Diagrams. Send \$3 check to cover copy & postage*
91. Installation procedure for a Heart Interface Power Inverter. Includes background information, detailed instructions, and computer generated illustrations. Bobb Partridge, Terrell, TX. (5)
92. Installing a Sony video backup monitor system in a Clark Coach. Includes installation procedures, operational notes, computer enhanced drawings, and comments on choice of equipment. Bobb Partridge, Terrell, TX. (2)
93. Work sketch for modifying a John Deere AM364T tractor muffler to fit Kohler 4kw generator. Allan Powell, Lewiston, NY.
94. Blueprint 11"x17" With Specifications, Dimensions, And Materials Needed To Construct A Work Platform To Facilitate Work About The Coach Gutter And Roof. Paul Clemensen, Albuquerque, NM.
95. A 4-Page Detailed Description, With Draftsman Quality Drawings, Of My '65 Cortez. Tim Verschuyl, Palo Alto, CA. (2)
96. Instructions & Drawings To Modify And Rebuild The Upper Shock Mount On The Clark Model Coaches. Jerry McMurry, Lakeside, CA.
97. Step Procedure for Replacing Old Vacuum Windshield Washer Pump with New 12v Electric Unit - Bill Townsend, Ventura, CA.
98. Procedure for Machining New 1/2" Studs for Lower Shock Mount to Replace Original Shock with 3/4" Eyelet - Lee Burton, Camas, WA.
99. This item combined with item 56.
100. A 24x30" Blueprint T-32MH4 12v Running Wiring Schematic for Kent Model. Send \$3 check to The National to cover copy & postage costs.
101. A 24x30" Blueprint Complete 12v Wiring Schematic for both Side & Rear Bath Kent Models. Send \$3 check to The National to cover copy & postage costs.
102. Winterizing Your RV For Winter Travel. Articles from Jan/Feb 1983 MotorHome Magazine. (4)
103. Window Screen Removal. Method utilizes wooden slats to spread window frame for easy removal of screens for rescreening. Bill Raborg, Frazier Park, CA.
104. Silent Block Procedure For Removal/Installation & List of Tools & Equipment Required. Milt Litwiller, Sarasota, FL. (2)
105. Servicing the Front Wheel Bearings & CV Joints, Kent Model - Doug Evans, Van Nuys, CA. (3)
106. Goodyear Tire Care & Warranty Information. (3)
107. Bendix Hydrovac Manual - Jerry McMurry, Lakeside, CA. (8)
108. Insulating and Sound Deadening Interior, Installing New Headliner - Larry Olsen, Chico, CA. (4)
109. Construction Plans for a Garage Service Pit for the Cortez - Frank Freda, Santa Barbara, CA (1)